


Tree Number: 3

Tree species: Carolina cherry

Roadway Clearance: One main leader is leaning and cracked.


Trunk intrudes into the roadway at 9 feet. Remove tree.



Tree Number: 4

Tree species: Live oak

Roadway Clearance: The main trunk is not an obstacle. The side branch should be pruned off, it's lowest point is 13 feet at the left road edge. Tree is not doing well, likely due root damage.



Tree Number: 5

Tree species: Live oak

Roadway Clearance: Limb is dead. Clearance on left road edge is 11.5 feet.
We recommend the removal of the horizontal branch
before it falls on someone.




Prune here

Looking up at branch.
Damaging fungi are present
on this branch.

Tree Number: 27

Tree species: Brazilian pepper

Roadway Clearance: This invasive shrub is encroaching the travel lanes on the west side of the road at 13.5 feet. We recommend removal.



Tree Number: 28

Tree species: Laurel oak

Roadway Clearance: This tree does not encroach the roadway, however it is dead and should be removed before it falls over.





CITY OF ORMOND BEACH

City Manager 22 S. Beach St. Ormond Beach, FL 32174 (386) 676-3200 Fax: (386) 676-3384

February 27, 2009

Resident
Riverside Drive
Ormond Beach, FL 32176

Dear Resident:

A meeting was held on January 15, 2009, at 6:00 pm at The Casements located at 25 Riverside Drive, Ormond Beach, FL. At that time representatives from Urban Forestry, the City Arborist and the Ormond Beach Fire Department answered all questions regarding the potential removal of vegetation from Riverside Drive. The meeting resulted in a "walk along" with the Ormond Beach Fire Department, City Arborist and the residents of Riverside Drive. The "walk along" provided necessary information to Riverside Drive residents as well as clearly defining the areas for pruning and tree removal.

The Riverside Drive residents and the Fire Department have agreed on the following pruning and tree removal:

1. Adjacent to the mailbox at 105 Riverside Dr.
Permit (09-00001275) issued for the Cherry Laurel removal
Page 13--in the Tree Evaluation Report
2. Across from driveway of 110 Riverside Dr.
Live Oak side branch pruning
Page 14--in the Tree Evaluation Report
3. Vacant lot, north of 127 Riverside Dr.
Live Oak horizontal limb pruning
Page 15--in the Tree Evaluation Report
4. Vacant lot across from 283 Riverside Dr.
Brazilian pepper removal
Page 38--in the Tree Report
5. 283 Riverside Dr.
Permit (09-00001475) issued for the Laurel Oak removal
Page 39--in the Tree Report

This letter is to inform you that the City of Ormond Beach, Urban Forestry Section, is scheduled to begin the pruning and removal (#1 - #5) of the marked vegetation on Friday, March 6, 2009, beginning at 8:00 a.m.

Respectfully,

Theodore S. MacLeod, P.E.
Assistant City Manager